

說明:

- 1.D86x40Tx50H CNC
- 2.
- 3.

說明:

- 1.
- 2.
- 3.

說明:

說明:

mm	mm	mm			
50 86 100 90	20 30 40	10 50	Φ10-2+2Hole Φ50-3+3Hole Φ50-3+3Hole	30/40# 60# 100# 200#	CNC

說明:

RPM		
4500	400-600mm/	3mm

說明:

Images:


說明:

**boreway**®



**Boreway Machinery Co., Ltd.**  
[www.diamondtools.top](http://www.diamondtools.top)  
[www.boreway.com](http://www.boreway.com)

**boreway**®



**Boreway Machinery Co., Ltd.**  
[www.diamondtools.top](http://www.diamondtools.top)  
[www.boreway.com](http://www.boreway.com)

□□□□:

□□□□□□□□□□

□□:□□□□□□□□□□□□□□605

□□:362342

□□:(+86)595-86990206

□□:(+86)595-86990220

**Skype:**boreway02

**Whatsapp:**(+86)18359335376

□□:Sherry\_154

□□:boreway02@boreway.net