

□□:

- 1. D100x40mmx50HCNC □□□□□□□□□□CNC□□□□□□□□□□□□
- 2. □□□□□□□□□□□□□□□□□□
- 3. □□□□□□□□□□□□

□□:

- 1. □□□□□□□□□□□□□□□□□□
- 2. □□□□□□□□□□
- 3. □□□□□□

□□:

□□□□□□□□:

□□/mm	□□□□/mm	□□/mm	□□	□□	□□
50 86 100 90	20 30 40	10 50	Φ10-2+2Hole Φ50-3+3Hole Φ50-3+3Hole	30/40# 60# 100# 200#	CNC□□□□□□□□□ □

□□□□□□□□□□□□□□□□□□□□□□:

RPM	□□□□	□□□□
4500	400-600mm/□	3mm

□□□□□□□□□□□□

Images:


□□□□□□□□□□□□□□□□

boreway®



Boreway Machinery Co., Ltd.
www.diamondtools.top
www.boreway.com

boreway®



Boreway Machinery Co., Ltd.
www.diamondtools.top
www.boreway.com

□□□□:

□□□□□□□□□□

□□:□□□□□□□□□□□□□□605

□□:362342

□□:(+86)595-86990206

□□:(+86)595-86990220

Skype:boreway02

Whatsapp:(+86)18359335376

□□:Sherry_154

□□:boreway02@boreway.net