

說明:

此圖為 D19/15 * 155 L * 25B 的 CNC 加工圖
圖中尺寸均以 mm 為單位
圖中尺寸均以 mm 為單位
圖中尺寸均以 mm 為單位

步驟:

1. 檢查圖紙
2. 準備材料
3. Good 檢查
4. H 檢查

說明:

此圖為 D19/15 * 155 L * 25B:

| 零件號 | 厚度 | 直徑 | 長度 | 重量 | 材料 | 公差 |
|---------------|-----------------|---------|--------|----|---------------|-------|
| BW-DDB-S01-01 | 6 mm (1/4") | D6xH11 | 100 mm | 4" | 5/8-11 M14 | ±0.05 |
| BW-DDB-S01-02 | 8 mm (5/16") | D8xH11 | 100 mm | 4" | 1/2 螺絲 | ±0.05 |
| BW-DDB-S01-03 | 10 mm (3/8") | D10xH11 | 100 mm | 4" | 10 mm | ±0.05 |
| BW-DDB-S01-04 | 12 mm | D12xH11 | 100 mm | 4" | | ±0.05 |
| BW-DDB-S01-05 | 13 mm (1/2") | D13xH11 | 100 mm | 4" | | ±0.05 |
| BW-DDB-S01-06 | 14 mm | D14xH11 | 100 mm | 4" | | ±0.05 |
| BW-DDB-S01-07 | 16 mm (5/8") | D16xH11 | 100 mm | 4" | | ±0.05 |
| BW-DDB-S01-08 | 18 mm | D18xH11 | 100 mm | 4" | | ±0.05 |

此圖為 D19/15 * 155 L * 25B:

說明:

此圖為 D19/15 * 155 L * 25B

boreway®



Boreway Machinery Co., Ltd.
www.diamondtools.top
www.boreway.com

□□□□:

□□□□□□□□□□ □□ □□ **D14 * 190 L * M14**

boreway®



Boreway Machinery Co., Ltd.
www.diamondtools.top
www.boreway.com