

ADR:
 Fickert "ADR" resin.Increase
 machine.decrease energy.Storage,
 Without

- 1.
2. Without

Fickert :

Fickert	T140	* 15 140 * 56 (20)	36 # 46 # 80 # 120 # 180 # 240 # 320 # 400 # 600 # 800 # 1200 # 1500 # 3000 # 6000 #	
	T170	* 15 170 * 56 (20)		

Fickert :

boreway®



Boreway Machinery Co., Ltd.
www.diamondtools.top
www.boreway.com

boreway®



Boreway Machinery Co., Ltd.
www.diamondtools.top
www.boreway.com