

□□ :

- □□ □□ □□ □□, **CNC** □□ □ □□ □ □□□□ □□□ □ □□□□□.
- □□□□ □□ **CNC** □□ □ □□ □ □□□, □□ □□□ □□ □□ □□□□ □□□□ □□□□. □□ □□□ □□□□ □□□□ □□ □□□ □ □□□□□.
- □□□ □□ □□□□ □□□ □□□□□ □□ □□□ □□ □□□□□□□□. □□ □□ □□□ □□□ □□□ □□ □□ □□□□□.
- **CNC** □□ □ **CNC** □□ □, □□□, □□□□, □□□, □□□, □□, □□ □ □ □□□ □□□ □□ □□□□ □□ □□ □□ □□ □□ □□ □□ □□□□.

□□ :

□□ □□□ □□□□ □□ **CNC** □□ □ □□ □ :

□□	□□□□ □□	□□ □□
100.mm.	20mm	50mm.

□□ □□ □□ □□□□ □□ □□□□ □□□ □□□ □□ □□ □□ □□□□□.

rpm.	□□ □□	□□ □□
4500.	400-600mm / □	3mm

□□□ □□□□ □□□□□ □□ □□ □□ □ □□□□ □□ :

□□	50mm, 86mm, 90mm, 100mm.
□□ □□ / mm.	20mm, 30mm, 4.0mm.
□□ □□	10mm, 50mm.
□□	Φ10-2 + 2 □ Φ10-3 + 3 □ Φ50-3 + 3 □
□□ □□	30 / 40 #, 60 #, 100 #, 200 #
□□	CNC □□ □ □□□ □ □□

□□ □□ □□ □□ □□□□□

□ □□ □□ □□□□ □□ □□□□□.□□ □□□□ □□□□ □□□

100mm □□ □□ □□ □□ □□ □□ □□ □□ :



D100x20Tx50H



D100x30Tx50H





D100x40Tx50H

□□:



Smoother Milling Without
Stone Edge Damage

High Efficiency & Long
Lifespan & Fast Milling Speed



Perfect Balance With Zero
Vibration And Stable
Performance

□□□ :

cnc. □□□□ □□□□ □ □ □□



boreway®



Boreway Machinery Co.,Ltd
www.diamondtools.top
www.boreway.net

boreway®



Boreway Machinery Co.,Ltd
www.diamondtools.top
www.boreway.net

boreway®







Boreway Machinery Co.,Ltd
www.diamondtools.top
www.boreway.net

□□:

□□ □□ :□□ □□

□□: CNC □□

cnc.□□□ illing □□ □ □ □





Fujian Nanan *boreway*® Machinery Co.,Ltd.



No.605 Huahui Center, Shitou Town 362342 Quanzhou, Fujian, China.



☎ : (+86) 595-86990206 /  ☎:(+86) 595-86990220



☎ / **WhatsApp** / **Wechat** :(+ 86) 18650679939.



✉: **boreway@boreway.com.**



Lyon Chang.